

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex
Telex No.: 24305

Telephone: ROYal 9166

Enclosure

8th April, 1960.

Classn (S)
AH/BS

Dear Sirs,

Motorship "CORILLA"

The Society's Surveyors at Singapore have reported that, when this ship was under survey in December last, the shell and upper deck plating was drill tested over the cargo tank length.

The results of this drill testing have been examined here and I enclose a copy of the Singapore Harbour Board's drawing No R/1456 on which we have indicated in red the renewals which will be necessary at the Special Survey due at the end of December, 1960. The recommendations for renewal of plating outside the cargo tank length and any amendments to the renewals now indicated that may be necessary will be made at the time of the Special Survey.

Yours faithfully,

Deputy

Clerk to the
Classification Committee.

c.c. ROTTERDAM
SINGAPORE

Messrs. Shell Tankers, N.V.,
Wolffhandelgebouw,
Postbox 874,
Rotterdam,
Holland.



© 2020

Lloyd's Register
Foundation

002674-06687-0041