

Corilla

It is submitted the Rev. Surveyors be referred to their letter of 15/4/35 regarding the M.S. "Rapana" in which they state that the thickness of the crank web parallel to the axis was 290 mm.

According to the approved plan the thickness of the crank web parallel to the axis is 290 mm in way of the journal and 267 in way of the pin; and the thickness round the eye hole 204 mm.

They should be requested to verify these dimensions.

By Ld. Bd. - 17/5



002674-002681-0083

74
13/3/38.
© 2020

Lloyd's Register
Foundation