

Received from Chief Ship Surveyor..... 22 APR 1959

NAME "JALAYAMUNA" REPORT Cal. 18769.  
AR. No.

standing Conditions of Class: See previous endorsement dated 22.1.59.

ACTION IS DEFERRED for S.S. by 5,59.

rsment of Certificate (As before ~~or None~~)

ays due: SPECIAL SURVEY (C) due 5,58. Postponement until 5,59  
approved 9,58.

re of Present Survey: (Afloat ~~and in dry dock~~)

Temporary repairs to shell plating in way of No.2 hold (s.s).

cial Features:

Interim Certificate in order (Yes-~~No-None~~)

ms Outstanding: (If any for S.S.) All items.

. to be completed by: 5,59.

ommendation: SUBJECT to shell plates G.7 & H.7 (p.s. from fwd.), No.3  
in 3rd below sheer (p & s) from aft), 'tween deck girders (p & s)  
in No.5 hold and to No.5 plate in 3rd strake below sheer (s.s)  
being specially examined and dealt with as necessary by the S.S.,  
to wasted shell plating in 2nd & 3rd strakes below sheer (p.s)  
abreast No.5 hatchway and No.3 in 2nd below sheer (s.s.a) being  
examined and dealt with as necessary, and to shell plate G.6 and  
internal structure in way (p.s.a) and shell plate No.5 in 3rd  
below sheer and No.4 in 4th below sheer (s.s.f) being specially  
examined and dealt with as necessary next drydocking, but FURTHER  
ACTION CONTINUE TO BE DEFERRED for S.S. by 5,59.

SUBJECT

IN S.R.L. APPENDIX.  
Indents in shell plating (p & s).



© 2020

Lloyd's Register  
Foundation

*Januar*  
17/4/59

002711-02716-0232