

A further copy has been sent to the Surveyors, Gothenburg

COPY

LLOYD'S REGISTER OF SHIPPING

Part of ROTTERDAM,

11th December, 1959.

48502.

This is to Certify that I have

Surveyed the Machinery of the motor tanker "CARLSHAMN", 8612 tons gross of Stockholm, whilst lying afloat at Kiddelburg on the 8th December, 1959 and subsequent dates for d.b.s.

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also that I will Recommend that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book d.b.s. 11-59, when the survey has been completed

and that her Machinery Classification Record be continued in the Book, subject to both furnaces of starboard boiler being repaired before the vessel is re-commissioned.

Parts now examined:

(C.S. Items only)

To complete the donkey boiler survey the safety valves of starboard boiler remain to be adjusted under steam, the exhaust gas boiler to be examined in its safety and its safety valves to be adjusted and the oil burning arrangements and remote controls to be examined as required.

[Signature]
Engineer Surveyor to Lloyd's Register.
G. Bons.

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it shall be understood that neither the Society nor any Member of its Committees is under any circumstances whatever to be held liable for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or Surveyors, or other Officers or Agents of the Society."

002725 - 002735 - 0130

