

Received from Chief Ship Surveyor.....

SHIP'S NAME Glan Campbell REPORT L.A. No. 4639Outstanding Conditions of Class:As beforeAction is deferred for S.S. by 9.61.S.R.L. Appendix. (As before or None)Surveys due: S.S.(C) due 6.60 - postponement until 9.61 approved previously.Nature of Present Survey: (Afloat and in dry dock)Temporary repairs due to flooding of no. 2 hold from deep tank.Special Features:Is Interim Certificate in order (Yes-No-None)Items Outstanding: (If any for S.S.)All.S.S. to be completed by:Recommendation:Subject as above and to bulkhead between no 2 hold and deep tanks being dealt with as necessary by the S.S. but Action cont. to be def. for SS by 9.61Subject.NOTE. It appears from H. Kong cable dated 21/9/61 that the ship is to be broken up.P. H. H. H. H.