

LDON

[Thin Copy for attaching to Report.]

LOYD'S REGISTER OF SHIPPING

Port NEWCASTLE UPON TYNE.

5th June, 1959.

NEWCASTLE-ON-TYNE, No.

116238

With reference to the Survey now being held on the

S.S. DRAKENSBERG CASTLE"

I beg to inform you that, in consequence of the condition of this vessel's **Port and**

Starboard Main Boiler Tubes

it will be my duty to recommend to the Committee that the same be **re-examined and**

re-examined and necessary. 19 59

September

As provided for in the Rules, an extract from which appears on the other side:—the continuance of the vessel's character in the Society's Register Book to be subject to the due fulfilment of this condition.

Yours faithfully,

R.P. Frazer

Engineer Surveyor to Lloyd's Register.


R.P. FRAZER.

The Union Castle Mail Steamship Co.

Technical Department, Limited,

4, St. Mary Axe,
LONDON. E.C.3.

002798 - 002807 - 0227



[Thin Copy for attaching to Report.]

COON

LLOYD'S REGISTER OF SHIPPING

Port NEWCASTLE UPON TYNE

Exp June, 1939

1102138

NEWCASTLE-ON-TYNE, ENGL.

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3.

Extract from the Rules of the Society respecting Surveys of Machinery:—

If, upon examination, it is found desirable that any part of machinery should be again examined before the date of the next survey certificate for a limited period will be granted in accordance with nature of the case.

Yours faithfully,



© 2020

Lloyd's Register Foundation



Survey gross purpo

and Shipp

me in that

Survey

and

sub main befo

Parts

(C)