


COPY

LLOYD'S REGISTER OF SHIPPING

C.1825

UNITED WITH THE BRITISH CORPORATION REGISTER



95, Bothwell Street,

Glasgow, 11th July, 1953.

C.2.

This is to Certify that

R. McLELLAN

The undersigned Surveyor to this Society did at the request of Messrs. G. & J. Weir Ltd.,

attend at their Cathcart works on the

11th June, 1953 and subsequently, for the purpose of examining and testing one 3" x 4½" x 6" Oil Fuel Pressure Pump

manufactured by them under Pump No. 275563

the order of Messrs. Todd Oil Burners Ltd.,

and intended for Order No. C4323/7547

The pump was examined under working conditions and the following results were obtained:—

Steam Pumps.		Motor Pumps.		Double Stroke or R.P.M.	Disch. Press. or Head (ft)	Galls. per hour
Steam Pressure.	Exh. Pressure.	Volts.	Amps.			
215	5.0	-	-	20	200	320

Pressures given are in lbs per square inch

The steam cylinder and pump body were tested hydraulically to 500/400 lb. per square inch respectively, and found sound and tight.

For identification purposes the pump was stamped:—
LLOYD'S TEST R.McL., with pressures and date.

(SGD.) R. McLELLAN

Surveyor to Lloyd's Register.

£2. - -

This is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be held responsible for any error or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society.