

## LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

## ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name "CAMBERWELL" Official No. 147619

Port of Registry London

This ship has been under survey at South Shields

on 24th October, and November 1956 and the following alterations to the conditions of assignment of loadlines have now been effected/~~found~~—

BRIDGE FORWARD BULKHEAD:--

W.T. door has been removed and opening plated over.  
Openings in bridge forward bulkhead now 2 openings  
with storm boards in channels and one opening with  
bolted steel plate.


Nos. 1 and 2 hatches on Freeboard deck.

Wire lashings have been dispensed with and locking bars  
fitted.

J. BALLANTINE.

21-11-56

A copy of this Report has been placed on board.



© 2021

Lloyd's Register  
Foundation

002816-002826-0059