

The class is subject to the condenser being re-examined
by 6.59.

4E

6 AUG 1958

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

SHIP'S NAME..... CAMBRIAN..... REPORT Sws..... No 26330

Damage to propeller. Docking. Screwshaft seen, and
spare propeller now fitted.

IT IS SUBMITTED that this vessel is eligible for THE
RECORD, TS 6.58, subject as above.



31.7.58.

Lloyd's Register
Foundation

002816-002824-0180