

LLOYD'S REGISTER OF SHIPPING
Nokyo Bldg., 161, Buzenda-cho,
Shimonoseki, Japan.

22nd July, 1961.

f.
asn.(S)

RECEIVED

26 JUL 1961

Dear Sir,

"ILEXIA" Shimonoseki Rpt.No.1778

In reply to your letter of 14th July, 1961 we have to confirm you that the leakage on J-12 plate (port side) in way of W.T. BHD, have now been temporary repaired by applying efficient doubler immediately above the existing doubler.

Repair hose tested and proved tight.

Regretting that it was not made clear in our report.

Yours faithfully,

[Signature]
For the Surveyors.

The Secretary,
LONDON.



© 2021

Lloyd's Register
Foundation

002816 - 002824 - 0313/

ここにも通信文を記載することができます

This space is also for correspondence.

折込線

PAR AVION
航空

THE SECRETARY,
LLOYD'S REGISTER OF SHIPPING,
71, Fenchurch Street,

LONDON E.C.2
England.

この郵便物には何物も封入又は添附できません
Nothing may be contained in or attached to this letter.

折込線

AEROGRAMME

45

REPORTS



© 2021

Lloyd's Register
Foundation

This space is also for correspondence.

ここにも通信文を記載することができます