



Lloyd's Register of Shipping,

13, Exchange,

Plymouth, 26th November 1921.

LLOYD'S REGISTER

LONDON

28 NOV 1921

REC'D
ANS'D

Sir,
With reference to the queries contained in your classing letter of the 1st instant in the case of the steamer "JAMES H BEAZLEY" Plymouth Report No:6110, I beg to report that the Statutory test of the Chain Cable supplied is as required by the Rules.

With regards to the breaking test of the stream wire the builders have been asked for a copy of the test certificate.

It is not understood what is meant by the "length of the erection" asked for in your letter, but as the vessel was completed in accordance with the sizes given on the approved plans which accompanied the reports, it may be possible to get the required length from the plans.

I am, Sir,

Your obedient servant,

The Secretary,

London.

Jas. C. Long



© 2020

Lloyd's Register
Foundation

002838-002845-0121

Referred to the Chief Ship Surveyor.

JAM.

28 NOV 1921

See for Mr. S. A. Hill to note.

Submitted the length of erection
See enclosure dated 26-10-21

to be recorded in the Register Book
JAM.
20-11-21

For Mr. White to note
& Mr. Drury

J. 12.21

as B.F. 78"



© 2020
Lloyd's Register
Foundation