

COPY

# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER



Port COLOMBO.

14th July, 1959.

4448

*This is to Certify that I have*

*surveyed the* Steel Screw s.s. "EFFIGYNY" 871 tons gross of  
Bombay and No.59103 in the Register Book, whilst the vessel  
lay afloat and in drydock at this port on the 26th June, 1959  
and subsequently on account of hull damage stated due to heavy  
weather encountered whilst vessel lay at anchorage in Colombo  
roads on the 22nd June, 1959, and also for purpose of commencement  
of the Special Survey,

*and that I have transmitted to the Committee of Lloyd's  
Register of Shipping, London, a Report stating that all repairs  
recommended by me have been completed to my satisfaction, and*

*that I have Recommended that ~~she be~~ the vessel is eligible  
to obtain a fresh record of docking 7,59, subject to all wasted  
deck, shell and keel plates being drill tested now and to  
any other outstanding conditions of class being dealt with as  
previously recommended.*

*being fit to carry*

  
(N.A. DAWSON)

Surveyor to Lloyd's Register.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed,  
it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be  
held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register  
or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member  
of the Surveyors, or other Officers or Agents of the Society."