

20 NOV 1957

Received from Chief Ship Surveyor

SHIP'S NAME "ESSO BELFAST" REPORT Msl. No. 12284.

Outstanding Conditions of Class: Subject to shellplate E.3 (p.s.a.) (thin) and upper deck plates (p & s) (thin) (recommended Lon. 7.11.57 to be renewed at next Special Survey, also bolts in upper deck longitudinal etc. being replaced by rivets before ship loads her usual cargos.

ACTION is DEFERRED for Special Survey.

Certificate (As before or None)

SPECIAL SURVEY (C) due 8,57. Postponement until a later date approved 7,57. Period of postponement dependent upon the reported results of the General Examination.

Place of Present Survey: (Afloat and in dry dock)

Subject item repair.

Special Features:

Interim Certificate in order (Yes - No - None)

Items Outstanding: (If any for S.S.)

ALL ITEMS.

Work to be completed by:

Recommendation:

SUBJECT to shellplate E3 (p.s.a.) (thin) and upper deck plates (p & s) (thin) (recommended Lon. 7.11.57 to be renewed at the Special Survey), without other condition, but with Endorsement of Certificate; ACTION be DEFERRED for Special Survey without special condition, with Endorsement of Certificate.

SUBJECT WITHOUT.

ENDORSEMENT OF CERTIFICATE. Shellplates H.5 & J.5 (p.s.f.) indented.

James 19/11/57



© 2020

Lloyd's Register Foundation