


LLOYD'S REGISTER OF SHIPPING

Port CAPE TOWN9th March, 1960**This is to Certify that I have**

Surveyed the machinery of the M.V. "NAMAQUA COAST" 246 tons gross of
own whilst afloat & on pontoon on 4th March, 1960 & subsequently, on
of Docking; Continuous Machinery Survey & General Examination in
postponement of SS.

and that I will transmit to the Committee of Lloyd's Register of
 Shipping, London, a Report stating that all recommendations made by
 me in connection therewith have been carried out to my satisfaction; also
 that I will Recommend that in the case of this Vessel the following
 Survey Records be made in the Supplement to the Register Book
 (CS) (with date) when the survey has been completed

and that her Machinery Classification Record be continued in the Book.

Parts now examined:**MAIN ENGINES:**

(C.S. Items only)

Nos. 3 & 4 Units: Cylinders, liners, pistons, rods, gudgeon pins &
 bushes, crankpins & bearings, cover, valves & valve gear, etc.
 Scavenge pump, complete.

Nos. 3 & 4 Main bearing journals & brasses.

Cam shaft.

Main thrust block.

Propeller, sea cocks & shell
 fastenings.

(SGD.) **C. RITCHIE**

Engineer Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
 CS Continuous Survey of Engines
 DBS Donkey Boiler Survey
 ES Engine Special Survey
 MBS Main Boiler Survey
 MES Modified Survey of Oil Engines
 OF Fitted for oil fuel (date) FP above 150°F.

SGS Steam Generator Survey
 SPS Steampipe Survey
 TS Tailshaft Survey
 TS(CL) Tailshaft Survey—Continuous Liner
 TSN Tailshaft renewed
 TS(OG) Tailshaft Survey—Oil Gland

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are
 fully executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any
 circumstances whatever to be held responsible for any inaccuracy in any report or Certificate issued by the Society or its
 Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default
 or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."