

14th October, 1948.

Dear Sir,

S.S. "TOMOCYCLUS"

S. With reference to Liverpool First Entry Report No.127547, it is concluded the ship's service air receiver has been examined, but I shall be glad if you will state if this is so. In addition, I think it well to inform you that the test of steam pipes need not be carried out until the vessel is eight years old, that is 1952, and a note will be placed in the Special Reasons List accordingly.

Yours faithfully,

Clerk to the
Classification Committee.

The Secretary,
LIVERPOOL.



© 2020

Lloyd's Register
Foundation

002858-002869-0354