

SHIP'S NAME "JAG VIJAY"

REPORT

Kob. No. 4258

Standing Conditions of Class:

Subject to cargo battens being fitted in original cross bunker space at the earliest opportunity, to starboard deep tank forward bulkhead stiffeners and indented shell plates E.6, F.7, D.7 & C.1 (p.s.a.) and No.1 in 4th below sheer (s.s.) being dealt with as necessary also to permanent repairs to No.2 No.2 tank top plating next Special Survey, and to the rudder stock being renewed by 10,56.

Assignment of Class (B) (~~As before~~ None)

Surveys due: SPECIAL SURVEY (C) due 10,56.

Condition of Present Survey: (Afloat and in dry dock)

Docking: Special Survey: Damage repairs (contact) and to all the deferred items as above: Alterations in accordance with approved plans

Special Features: Rudder stock now renewed.

Interim Certificate in order (Yes-No-None)

Outstanding: (If any for S.S. or A.S.)

NONE.

Work completed by

and <sup>4.5</sup> Mukaishima 2,57' SUBMITTED Notations 'DS 1,57' / be assigned but without special conditions.

DS 1,57 } Without.  
SS Mukaishima 2,57 }

AMEND R.B. to -  
DTsa pt W.B. 457t pt O.F.

IT IS FURTHER SUBMITTED the Surveyors be requested to furnish forging certificate for the rudder stock now renewed as this has not been sent with the report.

FREEBOARD SURVEYORS TO NOTE this report.

*See letter 225-57*

X 7/5



© *[Signature]*  
29-4-57

Lloyd's Register  
Foundation

002876-002882-0085