

~~Hawthorn Hill~~ Don Manuel  
N/N → \* F.E.

Received by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME Stl. Sw. Sc. M/V. "CARDIUM." Rpt. Nwc No. 8787H.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

<sup>1st</sup> Longitudinal  
Transverse No. 15300 Depth "d" ✓  
Framing: Table No. \_\_\_\_\_ Description Transverse framing at sides  
Longitudinal framing at bottom  
and at deck.  
<sup>2nd</sup> Longitudinal No. 43087 Proportions Length 13.24  
Depth = \_\_\_\_\_  
Deck Sheerstrake as approved

*Revised Rules.*


This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A1 (Steel). Carrying Petroleum in Bulk.  
1 D<sup>5</sup> (Stl), 2<sup>nd</sup> D<sup>5</sup> (Stl) clear of Cargo tanks.

Longitudinal framing at bottom and at deck.  
Cell D.B. U E 69' 244t, D.T. 32' 365t, F.P.T. 213t, A.P.T. 55t.  
F.K. 14 B.H. Lloyds A & C.P.

P 103', B 35', F 42'.

Machy aft.



© 2021

Lloyd's Register  
Foundation

002907-002915-0056