

Chief Surveyors.....

Received from Chief Surveyors.....

NAME "ENFORCER" REPORT Lth. No. 25089

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

of Survey Docking: Wear and tear repairs. When due.....

NOTED.

NOTE:- This ship is laid up at Rosyth.

ENGRS. SURVEYORS TO NOTE.

X



© 2020

Lloyd's Register  
Foundation

002916-002922-0011

*James*  
19/12/19