

Thin Copy for attaching to Report.]

# S REGISTER OF SHIPPING

Port.....LONDON

8th May 1962.

r.  
With reference to the Survey  
held on the m.v. "DOMINION MONARCH"  
ons gross of Southampton  
inform you that, in consequence of  
tion of this vessel's Stbd. outer Main  
abricated 'A' frame repair between  
t & scavenge pump crankcase,  
be my duty to recommend to the  
e that the same be again specially  
ed end of December 1962  
led for in the Rules, an extract from  
pears on the other side:—the continuance  
ssel's character in the Society's Register  
be subject to the due fulfilment of this

Yours faithfully,

R.G.R. Midford

Engineer Surveyor to Lloyd's Register.

R.G.R. MIDFORD.

intendent Engineer.

Savill Line, South Side,

Albert Dock.

n. E.16.

002947-002955-0192