



17, BATTERY PLACE,

NEW YORK 4, N. Y.

RECEIVED
24 JAN 1949
ANGS.....

January 14, 1949

Dear Mr. Sladden:

"TROCHISCUS"
Gal. Rpt. 5046

Referring to the inquiry contained in your letter of December 13th regarding the above mentioned case, the Surveyor states that the indented fore-castle sheerstrake plating (s.s.) was not dealt with at the time of survey on September 23, to October 8, 1948.

Yours faithfully,

R.J. Sladden, Esq.

LONDON



© 2020

Lloyd's Register
Foundation

002956-002969-0250

12

...the 9 Gaultney pumpkins, each pump
well air compressors & air receivers.

I
R

Noted
GMB



© 2020

Lloyd's Register
Foundation