

Received from Chief Ship Surveyor.....23 JAN 1958

NAME "EASBY" REPORT H.Kg. No. 13975

Working Conditions of Class: Subject to shell plates (p.s.a.) being examined and dealt with, to stokehold forward W.T.bulkhead being specially examined and dealt with as necessary by next drydocking by 10,57, and to poop deck plating being specially examined and dealt with as necessary by the Special Survey.

Content of Certificate (As before or None)

Content of Present Survey: (Afloat and in dry dock)

Working: Wear and tear repairs including/part subject items.

Recommendation:

SUBMITTED record of 'DS 12,57' be assigned, subject to A.P.tank bulkhead plating and indented shell plate H.5 (s.s.a.) also to poop deck plating being specially examined and dealt with by next Special Survey, without other conditions but with Endorsement of Certificate.

12,57 Subject
Without.

ENDORSEMENT OF CERTIFICATE

Conditions in shell plates (p & s).



© 2020

Lloyd's Register
Foundation

James
16/1/58

00997-003005-0024