

SHIP'S NAME "JANMADA" REPORT Madras No. 1543
GB

Outstanding Conditions of Class: SUBJECT to set up bottom shell plating and No.7 D.B.tank (leakage) being specially examined and dealt with as necessary by the Special Survey.

ACTION is DEFERRED for Special Survey.

S.R.L. Appendix. (As before ~~on None~~)

Surveys due: A SPECIAL SURVEY (C) became due 8,60 but postponement until 8,61 and subsequently 9,61 were approved. A further extension to cover voyage Cochin-Bombay was approved provided the ship was generally examined. It is stated the ship will be scraped at Bombay.

Nature of Present Survey: (Afloat and ~~in dry dock~~)

Ship generally examined for issue of LLST for voyage Cochin/Bombay in ballast.

Special Features: The year of grace expired 8,61.

Is Interim Certificate in order (Yes-~~None~~)

Items Outstanding: (If any for S.S.)

ALL ITEMS.

S.S. to be completed by:

Recommendation:

SUBJECT as above, but ACTION be DEFERRED for a Special Survey on ship's arrival at Bombay from present voyage.

SUBJECT

~~IN S.R.L. APPENDIX.~~

Indented sheerstrake and stringer plate abreast No.1 hatchway (s.s.) and shell plate No.6 in 1st below sheer (s.s.a).

OFFICE NOTE

Bottom stiffening fitted between frs.53 and 141.



WOT
8/11/61

Lloyd's Register
Foundation

003006-003012-0009