

5 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor.

26 Jan 1950

NAME

Stammar

REPORT

Rot.

No. 31898

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.


"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

Survey

~~DAMAGE &~~ WEAR AND TEAR.

a previous repair to the propelling motor spider further examined & found satisfactory.

It is submitted the vessel is eligible to remain as classed with
~~record of Survey~~ as recommended.



© 2021

Lloyd's Register
Foundation

003006 - 003012 - 0059

24/3/50.