

1

Received from Chief Surveyors

Sent Chief Surveyors

VESL'S NAME

Twin Sc.S.S. "CLAN FORBES"

Report

Grk.

No.

20662

For the CHIEF SHIP SURVEYOR, ~~IN CHIEF SHIP SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

of Survey

FIRST ENTRY

When due

✱ 100A1 "With Freeboard"

2 Dks. and Shelter Dk.


Cell.DB 393' 1266t, MT 30' 1076t, FPT 68t, APT 126t.

FK, Duct keel forward of Machinery space, 7BH(Coll.BH to Shelter Dk., 6BH to 2nd Dk.) pt.cem., Lloyd's A & CP

P 31, B 103', F 69'.

O.L. 487.6'

This is generally a sister vessel to the "CLAN BUCHANAN"



© 2021

Lloyd's Register
Foundation

003006-003012-0101