

Steering Gear, Type (Power hand)

Yonkin & Co. ✓

Alternative Means of Steering

Steering Chains (Size and Test)

Telemotor ✓

Windlass Clarke Chapman & Co.

Req. 1.

No. ⁶²⁶⁰
~~311~~

Port SUNDERLAND.

(Received at London Office,.....)

Date 18th September 1947

We request that the Single Screw Steamer

Building

for Stratton Steamship Co. by Wm. Pickersgill & Sons Limited,

of 2,200 Tons, Length, 310' breadth, 45' depth, 20'

may be Specially Surveyed while building (100 A1 (with Freeboard)) If for a particular term or class, state the same.

We hereby engage to pay the established Special Survey Fees as set forth in the Society's Rules, or any variation therefrom which has been duly notified and, in addition, any travelling and other expenses which may be incurred by the Surveyors in connection with the survey.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

No. 311 in Builder's Yard. Manufacturers of Engines The North Eastern Marine Engrs: Co. (1938) Ltd., SUNDERLAND.

Ditto of Boilers
FOR WM. PICKERSGILL & SONS, LIMITED.

Signature [Signature]

General Manager.

To the Secretary,
Lloyd's Register of Shipping,
71, Fenchurch Street, London, E.C.3.

NOTE.—To avoid misunderstanding, orders for materials requiring to be tested should be marked as follows:—
"Inspection and Testing by Lloyd's Register Surveyors to the Society's requirements."

003018-003022-0081

© 2020

Lloyd's Register
Foundation