

class is subject to

4E

received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

9-MAR1961

SHIP'S NAME.....

"GADINIA"

REPORT.....

CCO

6131.

ROT

No. 50945.


The Surveyor reports one blade tip of the starboard propeller found broken off in way of previous repair and the opposite blade tip now cropped and the Surveyors recommend that the class be made subject to the starboard propeller being repaired before the vessel is re-commissioned.

IT IS SUBMITTED that this vessel is eligible to remain as classed subject as recommended.



© 2020

6.3.61.



Lloyd's Register  
Foundation

003046-003055-0197