

COPY

LLOYD'S REGISTER OF SHIPPING



Port Willemstad, Curacao, N. A.

19th December, 1960.


This is to Certify *that I have*

Surveyed the Machinery of the S.S. "GADINIA" 6819 Gross Tons of London,
whilst vessel lying afloat at this port on 9th December 1960 and subse-
quently, for temporary repairs to starboard propeller,

and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report stating that all recommendations made by
me in connection therewith have been carried out to my satisfaction; also
that I will Recommend that in the case of this Vessel ~~the following~~ ^{no fresh}
Survey Records be made in the Supplement to the Register Book

and that her Machinery Classification Record be continued in the Book. '
subject to starboard propeller being renewed at next Drydocking.

Parts now examined:
(C.S. Items only)


(J. C. Nebels)

Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS

| | | | |
|-----|--|--------|-----------------------------------|
| ABS | Auxiliary Boiler Survey | SGS | Steam Generator Survey |
| CS | Continuous Survey of Engines | SPS | Steampipe Survey |
| DBS | Donkey Boiler Survey | TS | Tailshaft Survey |
| ES | Engine Special Survey | TS(CL) | Tailshaft Survey—Continuous Liner |
| MBS | Main Boiler Survey | TSN | Tailshaft renewed |
| MES | Modified Survey of Oil Engines | TS(OG) | Tailshaft Survey—Oil Gland |
| OF | Fitted for oil fuel (date) FP above 150°F. | | |

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 50m,3,58 (MADE AND PRINTED IN ENGLAND.)

003046-003055-0202