

11th December, 1959.

HONG KONG

RMC. 15150, 191 - As recommended.

RMC. 15183 "DEMODOCUS" - As recommended. It is noted that you have issued a Cert. A (RMC) in which the Running Survey notation is out of date as the ship has a later record of RB 9,59. When you are unable to obtain the necessary information regarding the position of surveys you should cable this Office for instructions. When time does not permit and you are unable to obtain written evidence that a Running Survey has been held either from the Survey Book or a certificate, you should get verbal confirmation on board that the survey has been completed, in which case you should add to the Cert. A(RMC), above the signature, the following statement:-

"There is no written evidence on board that the Running Survey has been completed, but it is stated on board that the Running Survey was completed at (Port) on (date)".

15036 "DONACILLA" - As recommended, except that class has been continued subject to shell plate D.8 and internal structure in way frame 100 (starboard side) and shell plates C.14 (scored and doubled) and D.12 (fractured and doubled) (port side from aft) and H.3 (wasted and doubled) (port and starboard) being specially examined and dealt with as necessary by the Special Survey.



© 2020

Lloyd's Register
Foundation

003046-003055-0325