

Lloyd's Register of Shipping,

Kungsgatan 8,

Helsingborg, 8th June, 1935.



LLOYD'S REGISTER
RECEIVED
11 JUN 1935
Ansd.
LONDON

The Secretary,
London.

Dear Sir,


With reference to your classing letter of the 4th instant and to our report No.913 on the steamer "MAURITZ", I beg to inform you that there is no plan of the pumping arrangement available. I may add that during the survey of the machinery of this vessel I satisfied myself regarding the pumping arrangement and their efficiency. Parts of same, not fulfilling the Rule requirements, was altered and placed in order as stated in our report on Form 9 forwarded on the 22nd May, 1935.

The electric installation was megger tested and found to fulfil the Rule requirements regarding insulation resistance.

I am, Dear Sir,

Yours faithfully,

X. Aker



Lloyd's Register
Foundation

003056-003064-0139

Shipping Register

Книжка 8

Heisingrod 88, June, 1935

RECEIVED
11 JUL 11 1935
LONDON & GYON

London.
The Secretary,
London.

Dear Sir,

With reference to your closing letter of the 4th instant

and to our report No. 212 on the steamer "MADRID", I beg to inform you that there is no plan of the pumping arrangement available. I am sorry that the survey of the machinery of this vessel was not completed and that the pumping arrangement and the efficiency of same, not following the rule requirements, was not stated in our report on the 1st of June. The electric installation was suggested and found to be satisfactory and the rule requirements were not followed in the installation of the electric installation. The electric installation was suggested and found to be satisfactory and the rule requirements were not followed in the installation of the electric installation.

Yours faithfully,
E. J. Spinks

11 JUN 1935

also for Mr. Spinks to note

Wid
of Y.
12/6/35

Referred to the Chief Ship Surveyor,
and the Chief Engineer Surveyor.