

COPY

CARDIFF 60430

LLOYD'S REGISTER OF SHIPPING



Port

CARDIFF

18th March, 1958.

This is to Certify that I have

Donkey part of the
 Surveyed the Boiler and Machinery of the M.V. "DEWDALE"
 8298 tons gross of London, whilst in dry dock and afloat at
 Newport, Mon. on the 3rd January, 1958 and subsequently for
 the DBS., TS. and Part CS.,
 and that I have transmitted to the Committee of Lloyd's
 Register of Shipping, London, a Report stating that all
 recommendations made by me in connection therewith have
 been carried out to my satisfaction, and that I have
 Recommended that the record of DBS (Donkey Boiler Survey)
 3-58, TS-CL (Tailshaft Survey - Continuous Liner) 3-58 and
 CS (Continuous Survey of Engines) with date
 be made in the Register Book in the case of this vessel when
 the survey has been completed.

Parts now examined :-

Propeller, engine room sea connections, fastenings, Screwshaft.
 Main Engine:-
 Nos. 4 & 5 cylinders, covers, pistons & rods, valves and gears,
 top ends and guides, crankpins and bearings, superchargers.
 Intermediate shaft and bearings.
 Auxiliary condenser (tested).
 Main engine attached pumps, sea water circulating, piston and
 jacket, both bilge.
 Forward and aft oil fuel unit pumps.
 Starboard fire pump.
 Aft oil fuel heater (tested).
 Upper and lower main air receivers and safety devices.

P.T.O.

B. Borkett

(B. BORKETT)

Engineer Surveyor to Lloyd's Register

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-
 "While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed,
 it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be
 held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register
 Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member
 thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B.1. (C.S.) 80m.1.57.

(MADE AND PRINTED IN ENGLAND.)

003075-003082-0119

Lloyd's Register
 Foundation

00430


CARDIFF

COPY

LLOYD'S REGISTER OF SHIPPING

- Evaporator.
- Steering machinery.
- Windlass.
- Port & starboard steam driven auxiliary generator engines.
- Forced draught fan engine.

Port and starboard donkey boilers in their entirety.
Oil burning and steam smothering systems and remote controls under working conditions.



This is to Certify that I have


Surveyed the Boiler and Machinery of the
and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all
recommendations made by me in connection therewith have
been carried out to my satisfaction, and that I have
Recommended that the record of
be made in the Register Book in the case of this vessel when
the survey has been completed.

Parts now examined:-

Propeller, engine room connections, fastenings, coverings,
boiler, M.C. cylinders, covers, pistons & rods, valves and gear,
top and sides, crankpins and bearings, superheaters,
intermediate shaft and bearings,
Auxiliary condenser (tested),
Main engine attached pump, sea water circulating, piston and
rod, both sides,
forward and aft twin air pumps,
Starboard life pump,
aft oil fuel heater (tested),
upper and lower main air receivers and safety devices.

R. J. Barker
Engineer Surveyor to Lloyd's Register

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-
While the Committee of the Society use their best endeavours to ensure that the functions of the Society are properly executed,
it is to be understood that neither the Society nor any Member of its Committee is under any circumstances whatever to be
responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register
or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member
of the Surveyors or other Officers or Agents of the Society.



Lloyd's Register
Foundation