

005083-005091-0129

00,10,47.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME PAN REPORT Off. No. 56167

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

This vessel, which was built by the S. Western S.B. Co. in 1920, is classed in the American Bureau Register Book.

She at present holds the notations of 100A1 (Classification Contemplated) and "Examined 7.47".

At present she is undergoing Classification Survey at BARRY, and the Surveyors have forwarded particulars of the thicknesses of the shell plating, as ascertained by drilling. These have been examined and compared with the approved plans for a sister vessel, and are such as to merit approval.

It is concluded the thicknesses of the Poop, Bridge, Forecastle, Bilge and bottom, shell plating - which have not been drill-tested - will be furnished in due course.

It might be pointed out to the Surveyors that the Drilling Sheet forwarded by them has not been set out in a proper manner, but it is concluded the particulars amidships and those at the forward end have been transposed.

GA
14.8.48



© 2020

Lloyd's Register Foundation