

"PAN".

Gen. Exam: Vessel in drydock.

Examined the propeller, sea valves & fastenings.

Examined M.P. crankpin & bottom end, N:1

Journal & main bearing, the fan engine,

Starboard dynamo engine, auxiliary condenser,

electric installation.

Selected main & auxiliary steam pipes removed, tested to rule requirements & refitted.

The machinery examined generally, and the essential pumps examined under working conditions.

Part MS: It is requested that the following be counted towards M.S., to be advanced at first opportunity:—

The steam pipes tested as above,

Fan engine,

Starb. Dynamo engine,

Auxiliary condenser,

Propeller and sea valves.

Minor repairs effected.

Licence checked.

C. Reed

It is stated that the screwshaft was last seen 6.45,

when a new shaft is stated to have been fitted

C. R.

Electrical Equipment generally examined under working conditions & found in efficient condition. Minor repairs effected

A. H.



© 2020

Lloyd's Register
Foundation