

Received from Chief Ship Surveyor

- 8 APR 1960

SHIP'S NAME "THALAMUS" REPORT Lon. No. 142256

GB

Outstanding Conditions of Class: NONE.

R.L. Appendix. (As before ~~or None~~)

Structure of Present Survey: (Afloat and in dry dock)

Docking: Permanent repairs to contact damage.

Commendation: SUBMITTED record of 'DS 2,60' be assigned.

DS 2,60.


IN S.R.L. APPENDIX.

Some keel, bottom and side shell plates (p & s) slightly indented.
Webs of transverse bulkheads in centre tanks buckled.

OFFICE NOTE

Structure reinforced - Sou. 12,52.
Docking barckets fitted - Nwc. 11,53.

NOTE:- The Owners state that after undocking the ship will be
laid up in the River Blackwater.



© 2020

Lloyd's Register
Foundation

003083-003091-0207

D-5-c
31/3/60