

COPY

Owner's name

CHRISTIAN S

Port

BBA.

No. 4736

Ship is subject to

NIL.

Last survey date

4.11.62

E.S. due 11.61 - now held.


H.B.S. due 4.62 partly held A & Z now completely rehld.

Recking. Upward down - 2.5 m

General repairs effected to main & aux machinery and  
generating tubes renewed in Port & Starboard boilers.

The Damage Report for defects attributed to have been  
sustained due to contamination of oil fuel by leaking  
oil heating lines in deep tank with subsequent loss of  
power necessitating vessel being towed into Port of Refuge.

It is submitted that this  
vessel is eligible to remain  
as **CLASSED.**



Lloyd's Register  
Foundation

003116-003123-0091

ALSO FOR