

Esperance

N/N. TITANIAN

N.T.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Stl Se M/V MORGENEN Rpt. huc No. 86364

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).


1st Long
 Transverse No. 14586 Depth "d" 21.66
 Framing: Table No. ✓ Description Longitudinal framing
 2^d Longitudinal No. H0443
 Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{13.33}{1.02}$
 Deck Sheerstrake 1.02, approved .87



Revised Rules.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A.1. (Steel) Carrying Petroleum in Bulk.
 2 D^{cs} (Stl) + web frames, Longitudinal framing
 Cell D.B. u E 65' 236t, D.T. f 41' 458t, F.P.T. 113t, A.P.T. 116t
 FK, 16 B.H. (11 B.H. to upper D^c, 5 B.H. to 2^d D^c) ft Cen, Lloyd ACP.
 P 110', B 31', F H2'.
 machy aft.



© 2020
 27.10.30
 Lloyd's Register Foundation