


COPY

LLOYD'S REGISTER OF SHIPPING

6334



Port B r e m e n

14th March, 1962.

This is to Certify that I have

Surveyed the Machinery of the M.V. "KIRSTEN SKOU", 4153 tons gross of Copenhagen, whilst lying in drydock at Bremen-Vegesack on the 13th March, 1962 and subsequently for drydocking, Screwshaft Survey and advancement of CS,

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also that I will Recommend that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book TS(CL) 3/62 now and CS (with date) when the Survey has been completed and that her Machinery Classification Record be continued in the Book.

Parts now examined:

(C.S. Items only)

Propeller and outside fastenings of sea connections
S. forward O.P. transfer pump
P. bilge-/ sanitary pump.

H.G. Ellerbrock

Engineer Surveyor to Lloyd's Register

(H.G. Ellerbrock)

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register-Book or other publication of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 150m,5,60 (MADE AND PRINTED IN ENGLAND)

© 2020

Lloyd's Register
Foundation

003147-003153-0226