

Rpt. 25 **WRECK SECTION**
No. 762

RD 53487

WRECK SECTION
No. 762

REPORT OF TOTAL LOSS, CASUALTY, BREAKING UP, ETC.

Ship's Name **SS/MS "BANDON"** Gross tons **395** Date of Build **10-1951**
Casualty notice sent to Owners **7.11.62.** Owners' Reply **15.11.62.** Owners **Thai Navigation Co., Ltd.**

Details of classification

+100A1	+LMC CS8,59
Gulf of Thailand	
service	ts p5,62
10,61	CL
ss 8,59	s8,60

Details of casualty

This ship foundered off Patani, southern Thailand during storm but the owners state that they cannot yet declare a total loss.

Date of casualty **25th October, 1962.**

SOURCE OF INFORMATION

LL 30/10/62

BANDON.—Bangkok, Oct. 29.—Motor vessel Bandon, owners Thai Navigation Co., Ltd., sank off Patani on Oct. 25.

LL 31/10/62

The Thai Navigation Co., Ltd., reported that motor vessel BANDON, 395 tons gross, had sunk during the storm. A few of the 47 passengers and crew were known to have survived. They were picked up off the Malayan coast. Two barges being towed by the vessel broke away during the storm.—Reuter. (See issue of Oct. 30, also BANDON under "Marine Casualties" in issue of Oct. 30.)

RETAIN

m/m
1972


Suggested record **"FOUNDERED 10,62"**

Date of Committee

Minute

FRIDAY 23 NOV 1962
Foundered 10.62

© 2020



Lloyd's Register
Foundation

NOTED FOR POSTING

Header