

s name

"CORNISH CITY"

Port

Lth.

No. 25228

Last survey date 10.10.62.

s is subject to sternframe back post at top and bottom
gudgeons (E.W.6,60) being specially examined and to indented
shell plates H.2 & J.2 (s.s.a) being examined and dealt
with as necessary at the next drydocking.

L. Appendix (as before ~~xxx none~~)

re of present survey (afloat and in drydock)

Docking: Examination on account of contact damage.

N O T E D.

XXXXXXXXXXXX
Recommendation

SUBJECT to indented shell plates
J.3 with internal structure in way (s.s.f)
and H.2 and J.2 (s.s.a) being specially
examined and dealt with as found necessary
by the next drydocking.

S.R.L. APPENDIX NOTE (AMENDED).

A few side shell plates etc. (p & s) indented.
Sternframe back post at top and
bottom gudgeons E.W.6,60.

C.S.S. Records Dept.
to note.

© 2020

Lloyd's Register
Foundation

003181-003190-0252