

1

fair hd.

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel Screw "THE EARL" Report Gls. No. 57137**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey First Entry When due --

100A1

1 Dk.

Cell. DB 132' 204t, FPR 65t, APT 29t.

FK, 3 BH, Cem. Lloyd's A & CP.

Q 114' B 9' F 31'

Machy. Aft.



This is a sister ship to the "THE PRESIDENT"



© 2020

19 6 36

Lloyd's Register
Foundation

003217-003222-0051