

Proposal to carry out SPECIAL SURVEY(C) (due 5,58) in
July next approved 6.3.58.

Surveyors.....

Received from Chief Surveyors.....

NAME "SPRAYVILLE" REPORT Liv. No. 148784.
JB

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

Survey S.R.L. When due.....

NOTED

SUBJECT to indented shell plates D.3, E.2 & 3
etc.(p.s.f.) being examined and dealt with as
necessary also to keel plate No.1 from fwd. being
renewed at the Special Survey.

ENDORSEMENT OF CERTIFICATE.

Keel plate Nos.5 & shell plate No.9
in 'A' strake (p.s.) set up.
Stem and stem plates buckled.
Bilge plating in way of No.2 hold
(s.s.a.) indented.
Rudderstock twisted 5°.

C. M. 14.3.58



© 2020

Lloyd's Register
Foundation

003223-003232-0151