


11th August, 1947

The Secretary,
Lloyd's Register of Shipping,
London.

Dear Sir,

M.S. "African Reefer" No. 12196 in
the Register Book.

With reference to your classing letter of the
8th August last regarding the shifting beams, we have to state
that the beams are fitted as indicated on the midship section.



Yours faithfully,

Lloyd's Register
Foundation

003245-003251-0085