

"TEDDY"

Grk. 23493.

Submitted the Greenock Surveyors be asked to confirm whether the material test results on the working bronze propeller comply with the requirements of Section 11 of the Rules for Quality and Testing of Materials, in view of the desired notation of "Strengthened for Navigation in Ice".

In view of the small size of the vessel, they should also state whether the machinery spare gear supplied is for full service or for "short voyages" only. If the former, the spare propeller should also comply with the Rules for Ice "avigation.

The Surveyors remarks are awaited so that this case can receive attention.



EW.
© 2020
12. 6. 47.

Lloyd's Register
Foundation

003252-003262-0058