

SEI

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex
Telex No.: 24305

Telephone: ROYal 9166

8th July, 1960.

assn. (H)

Dear Sir,

S.S. "JONANCY"

With reference to the second and third paragraphs of my letter dated the 9th May last, to which I do not appear to have received a reply, I shall be glad to learn for the early information of the Committee, what is the present position regarding the hull condition of class, requiring that the midship deep tank top plating be examined and dealt with as found necessary on the ship's arrival at Valparaiso, as recommended by the Newport News Surveyors following the survey completed so long ago as the 18th January, 1960.

Information is also awaited as to the Owners' intentions with regard to the completion of the Engine Survey by the examination of the items given in my letter referred to above and the installation of an emergency fire pump.

Yours faithfully,

Clerk to the
Classification Committee.

The Secretary,
NEW YORK.



© 2020

Lloyd's Register
Foundation

003252-003262-0106