



LLOYD'S REGISTER OF SHIPPING

Ref: Classn(H).

Calle 25 de Mayo 158,

BUENOS AIRES, 29th. July 1957.

communications to be addressed to
THE SURVEYORS

RECEIVED

6 - AUG 1957 Dear Sir,

Ans'd.....

Motorship "LA PLATA". 737 $\frac{1}{4}$ tons)

With reference to your letter of the 23rd. instant, we regret to inform you that the above named vessel was entered in our Return 3 in error, as the entry in the Surveyor's Journal was only noted as a memo.

For your information we quote hereunder the entry in Mr. W.F. Rogeron's Journal.

24-4-57. "La Plata" Examined two cylinder covers repaired by Memo only. Metalook.

Both tested under 5 Kg./sq.cm. and found leaking. (Covers were removed from M.E. and spares fitted by Ship Engineers).

Chief informed covers not acceptable and states new spares will be obtained on return to Europe.

We regret any inconvenience caused in this matter.

Yours faithfully.

for The Surveyors.

J White

The Secretary.
LONDON.



© 2020

Lloyd's Register
Foundation

003298-003306-0176

CLASSIFICATION

H Tom R. A. F.

LONDON.
The Secretary.

The Secretary.

The Secretary.

The Secretary.

The Secretary.

The Secretary.

The Secretary.

The Secretary.

The Secretary.

The Secretary.

The Secretary.

The Secretary.

The Secretary.

The Secretary.

The Secretary.

The Secretary.

The Secretary.

The Secretary.

The Secretary.

The Secretary.

The Secretary.

© 2020

Lloyd's Register
Foundation

The Secretary.

LLOYD'S REGISTER OF SHIPPING

The Secretary.

The Secretary.