



# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

C/H

## KIEL, Holstenbrücke 2, 3rd floor

Telegrams: Lloydsregister, Kiel

Telephone: No. 4 12 30

Reference:

822/H/F.

RECEIVED

22nd May, 1954

24 MAY 1954

Ans d.....

Dear Sir,

M.T. "ESSO KÖBENHAVN"

We forward herewith Rpts. 8, 9, 6 (Fg.), Certs. B and B 1 in the case of the above ship.

Plans and certificates as follows are attached:

1. No. SKR 5 - Enlarging of aux. Diesel Seating
2. No. MKE 933 - Principal Wiring Diagram for Main Switchboard
3. Copenhagen Rpt. 10 on one heavy oil engine no. 1087
4. Works Test Hansa Motorenfabrik on generator No. 554212
5. " " Ruhrstahl A.G. on one crankshaft
6. Copenhagen Rpt. 6 No. 8138 on 4 conn. rods for aux. engine
7. " " 6 " 7868 on one propeller shaft with CL

Photostat copy of Rpt. C 11 is returned herewith, also F.E. rpt. NWC No. 86440, forwarded with your letter of the 15th March, 1954.

Fees as follows should be charged to the Owners:

<u>SK No. 349</u>	
Part of Special Survey Fee	£ 40. 0. 0 ✓
Special Damage Repair fee	250. 0. 0 ✓
Special Repair Fee(W+T)Hull	35. 0. 0 ✓
Expenses	18.16. 0 ✓
DBS	20. 0. 0 ✓
Machinery addition	25. 0. 0 ✓
Special damage + Repair Fee including LMC	275. 0. 0 ✓
Sunday Fee 16.5.1954	5. 5. 0 ✓
Expenses	16. 0. 0 ✓

645. 1. 0

Ans to Gen 24/5/54

Yours faithfully,

Encl.

The Secretary  
London



For the Surveyors.

Lloyd's Register  
Foundation

003298-003306-0222

CLASSIFICATION

ACCOUNTS *int*

ADMIN/SM.

*ll*

*EX*



© 2020

Lloyd's Register  
Foundation

ROYAL SOCIETY OF MEDICINE  
LLOYD'S REGISTER OF SHIPPING

Bo  
en  
1.B  
On  
cup  
7  
at S  
Nure  
enbe  
r can  
face  
e dlat  
lag  
/ off  
RBS  
Age  
DO