

THROUGH OSLO
COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex
Telex No.: 24305

Telephone: ROYal 9166

14th September, 1961.

Dear Sirs,

Motorship "BRITAMER"

The Society's Surveyor at Chittagong has reported that some repairs were carried out last month to the main engine.

It was recommended that the No.3 main engine centre guide shoe should be specially examined by the end of next month, and class has been continued by the Committee subject, inter alia, to this matter receiving attention.

Your proposals regarding this item will be appreciated in due course.

Yours faithfully,

c.c. OSLO.

pro Clerk to the
Classification Committee.

Messrs. D/S A/S Baltimore,
Skippergt No.22,
OSLO,
Norway.



© 2020

Lloyd's Register
Foundation

003298-003306-0345