

17 NOV 1960

Received from Chief Ship Surveyor

SHIPS NAME "NERITINA" REPORT SNG No. 14275

EA

Outstanding Conditions of Class: NONE

ACTION is DEFERRED for examination
in drydock after grounding.

S.R.L. Appendix. (~~As before or None~~)

Nature of Present Survey: (Afloat and in dry dock)

Temporary repairs to wear and tear damage.
Pre Special Survey examination.
Drilling carried out in accordance with Circ. 2106 -
relevant drilling plan not forwarded yet.

Recommendation:

IT IS SUBMITTED this ship is eligible to continue as
classed and to have record of DS 10,60 assigned as
recommended, subject to poop deck plating aft being
permanently repaired by the Special Survey.

DS 10,60 Subject.

~~DELETE FROM S.R.L.
Drydocking (grounding).~~



© 2020

Lloyd's Register
Foundation