

# Lloyd's Register of Shipping.

13 SEP 1950



Port GLASGOW.

11th May, 1950.

This is to Certify that

E. EARNSHAW.

the undersigned Surveyor to this Society did at the request of Messrs. Clyde Fuel Systems Ltd., attend at their works at Hillington, Glasgow on the 1st May 1950, and subsequently for the purpose of examining and testing oil fuel components made to the order of Messrs. Cammell Laird & Co., Ltd., and intended for the s.s. "TETELA" Installation No. 4131.

The component parts comprise:-

1 - No. 5 Duplex P & H Unit comprising:

- 2 - C.I. Heater Bodies.
- 2 - C.I. Oil End Covers.
- 1 - C.I. 2" Pump Double Discharge Valve.
- 1 - M.S. Fabricated Air Vessel.
- 2 - C.I. 2½" Right Angle Heater Inlet Valves.
- 1 - C.I. 1½" " " " Discharge Valve.
- 1 - M.S. Fabricated Thermostat Holder.
- 2 - C.I. 1½" Discharge Valves.
- 1 - C.I. Duplex Discharge Strainer.
- 1 - M.S. " " " Wall Bracket.
- 16 - C.I. Burner & Thermometer Connections.
- 4 - C.I. 1" Circulating Valves.
- 4 - C.I. 1" Non-Return Valves (Quick Closing).
- 1 - C.I. Double Acting Hand Pump & Air Vessel.

All tested to 400 lbs per square inch.

- 2 - C.I. Steam Ends.
- 2 - C.I. Steam End Covers.
- 1 - G.M. 1" x ½" x ½" x ½" Steam Distribution Piece.
- 1 - G.M. ½" x ½" x ½" Steam Tee Piece.

All tested to 500 lbs per square inch.

- 2 - 4" x 6" x 7" Weir's Vertical O.F. Pumps. 1 off R.H. Serial No. 217769, 1 off L.H. Serial No. 240569, both previously tested at makers works.

*E. Earnshaw*

SURVEYOR TO LLOYD'S REGISTER.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."