


LLOYD'S REGISTER OF SHIPPING



/P.

NEWCASTLE-ON-TYNE. No 116879

Port NEWCASTLE UPON TYNE.

7th March, 1960.

This is to Certify that I have

Surveyed the Machinery of the S.S. "THE DUKE", 820 tons gross of Glasgow,
 whilst afloat and beached at South Shields on the 17th February, 1960 and
 subsequently, for the purpose of Main Boiler Survey and Boiler Repairs,
Tailshaft Survey,

and that I will transmit to the Committee of Lloyd's Register of
 Shipping, London, a Report stating that all recommendations made by
 me in connection therewith have been carried out to my satisfaction; also
 that I will Recommend that in the case of this Vessel the following
 Survey Records be made in the Supplement to the Register Book

M.B.S. 3.60 T.S. (C.L.) 3.60,

and that her Machinery Classification Record be continued in the Book,
 without condition regarding the main boiler front end plate below centre furnace.

Parts now examined:

(C.S. Items only)

T. J. McGinness

Engineer Surveyor to Lloyd's Register

T. J. MCGINNESS.

KEY TO ABBREVIATIONS


ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 50m,3,58 (MADE AND PRINTED IN ENGLAND.)

© 2020



Lloyd's Register
 Foundation

003311-003320-0202