

GAB

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex
Telex No.: 24305

Telephone: ROYal 9166

Enclosure.

25th March, 1960.

Dear Sirs,

M.S. "ELENI"

With reference to the Special Survey, due at the end of this month, I enclose herewith a copy of a letter dated the 24th March received from the Owners, also a copy of my reply today. It is understood the machinery items as detailed will be dealt with at Piraeus now.


According to our present records, to complete the Auxiliary Boiler Survey and entitle the vessel to a fresh record of 12.59 the mountings of the starboard boiler require to be examined, stoppered fire tubes renewed, the safety valves of both boilers adjusted under steam and the fuel oil burning arrangement and remote controls examined under working conditions. It is understood this inspection has recently been completed at Venice but we have no confirmation of this yet from our Surveyors.

The vessel's class is subject to No. 4 plate in 1st strake above sheer (s.s.a) being dealt with as necessary and to indented sheer strake and strake below No. 3 from forward (starboard side) and bilge keel (port side) being specially examined and dealt with as found necessary by the Special Survey.

Yours faithfully,

The Surveyors,
PIRAEUS.
c.c. Venice.

Clerk to the
Classification Committee.



© 2020

Lloyd's Register
Foundation

003324-003332-0098